

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2026

Submitted Date:

03/19/2026

Document Number:

701104602

**FIELD INSPECTION FORM**

Loc ID: 312384 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10770  
Name of Operator: VISION ENERGY LLC  
Address: P O BOX 370  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		pbechtolt@maralexinc.com	
,		mollieo@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221432	WELL	TA	01/01/2021	GW	077-08032	FEDERAL 1-1-1-1	EG

**General Comment:**

Flowline Integrity Inspection  
2 flowline risers capped at well head without OOSLAT tags.  
Install OOSLAT tags to risers.  
CA Date 4/20/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Flow Line	# 2				
Comment:	2 flowline risers capped at well head without OOSLAT tags.				
Corrective Action:	Install OOSLAT tags to risers.			Date:	04/20/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 221432 Type: WELL API Number: 077-08032 Status: TA Insp. Status: EG

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECOM Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104603	Flowline integrity inspection 701104602 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487349">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487349</a>