

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2026

Submitted Date:

03/19/2026

Document Number:

701104604

**FIELD INSPECTION FORM**

Loc ID 334678 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266196	WELL	PR	05/28/2004	GW	045-09127	GMR 9-14B (N9B)	EG
272651	WELL	PR	08/01/2025	GW	045-10117	GMR 9-11 (N9B)	EG
272654	WELL	PR	11/23/2004	GW	045-10118	HMU 9-12 (N9B)	EG
272658	WELL	PR	11/30/2008	GW	045-10124	HMU 913C (N9B)	EG
272660	WELL	PR	11/29/2004	GW	045-10122	HMU 9-15 (N9B)	EG
272661	WELL	PR	11/30/2004	GW	045-10121	HMU 9-10D (N9B)	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Uninsulated tank is rusted out at top seam of lid.  
Comply with Rules 608.a.(10) Tank Venting Standards and 608.e Mechanical Conditions.  
CA Date 4/4/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		,
Comment:	Uninsolated tank is rusted out at top seam of lid.				
Corrective Action:	Comply with Rules 608.a.(10) Tank Venting Standards and 608.e Mechanical Conditions.				Date: <u>04/04/2026</u>

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 266196 Type: WELL API Number: 045-09127 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272651 Type: WELL API Number: 045-10117 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272654 Type: WELL API Number: 045-10118 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272658 Type: WELL API Number: 045-10124 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272660 Type: WELL API Number: 045-10122 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272661 Type: WELL API Number: 045-10121 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104605	Flowline integrity inspection 701104604 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487350">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487350</a>