

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2026

Submitted Date:

03/13/2026

Document Number:

719500964

FIELD INSPECTION FORM

Loc ID 335917 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10844
 Name of Operator: QB ENERGY OPERATING LLC
 Address: 1001 17TH STREET SUITE 1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294152	WELL	PR	11/12/2009	GW	045-15279	CHEVRON 33-18D	PR
294153	WELL	PR	06/01/2024	GW	045-15280	CHEVRON 33-19D	PR
294154	WELL	SI	07/01/2025	GW	045-15281	CHEVRON 33-22D	SI
294155	WELL	SI	11/01/2025	GW	045-15282	CHEVRON 33-24D	SI
294156	WELL	PR	09/18/2009	GW	045-15283	CHEVRON 33-23D	PR
294157	WELL	SI	05/01/2025	GW	045-15284	CHEVRON 33-21D	SI
294159	WELL	PR	09/20/2009	GW	045-15286	CHEVRON 33-20D	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 3/12/2026 at approximately 15:35, Compliance Inspector Matthew Morris conducted a follow-up audit at QB ENERGY OPERATING LLC, CHEVRON E33 596 at Location ID #335917 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/(970)285-2615		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____
 Comment: _____
 Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	Unmarked deadman near wellheads.		
Corrective Action:	Mark deadman to comply with CECMC rules.		Date: 01/04/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 294152 Type: WELL API Number: 045-15279 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294153 Type: WELL API Number: 045-15280 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294154 Type: WELL API Number: 045-15281 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294155 Type: WELL API Number: 045-15282 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294156 Type: WELL API Number: 045-15283 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294157 Type: WELL API Number: 045-15284 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294159 Type: WELL API Number: 045-15286 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:	Date:
--------------------	-------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
		Culverts				
		Gravel				
Compaction						
		Ditches				
		Compaction				
				Material Handling And Spill Prevention		
		Check Dams				
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Unmarked deadman near wellheads</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	03/13/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404580110	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7480525
719500965	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7480523