


Inspection Photos
Location Name: Jones 32-18
API: 05-125-11698



Lease sign



Wellhead

Inspection Photos
Location Name: Jones 32-18
API: 05-125-11698



Meter run

VGS

Inspection Photos
Location Name: Jones 32-18
API: 05-125-11698



2 track erosion