

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2026

Submitted Date:

03/20/2026

Document Number:

710500757

FIELD INSPECTION FORM

Loc ID: 324811 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10777

Name of Operator: RAMPIKE RESOURCES LTD

Address: 730 17TH STREET SUITE 999

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Sharp, Neil	(720) 464-7603	nsharp@rampikeresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212822	WELL	PR	06/01/2024	OW	061-06182	PYLES 4	EI
324811	LOCATION	AC			-	PYLES-619S45W 10SENW	EI

General Comment:

This is an Environmental Inspection for the Pyles 4 Well Location located in Kiowa County, Colorado.

Pyles 4
Well Location ID: 324811
API #: 05-061-06182
Tank Battery: 484587

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
Crude Oil	Flow Line			
Comment:	At the time of inspection, oil was observed along the flowline corridor. ECMC Staff reported the release of fluids to Rampike Lease Operator on 3/19/2026. The Lease Operator shut in the well upon arrival and began a surface investigation.			
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free in accordance with Rule 912.b.			Date: <u>03/20/2026</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 212822 Type: WELL API Number: 061-06182 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324811 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500758	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488038