

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2026

Submitted Date:

03/20/2026

Document Number:

721100271

FIELD INSPECTION FORM

Loc ID 313569 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	
General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224508	WELL	PR	03/06/2018	CO2	083-06573	SAND CANYON 9	PR

General Comment:

On Friday, March 20, 2026 at 15:00 hours, southwest compliance specialist Jamie Blair performed a producing well compliance inspection and audit. No corrective actions were identified. Photos are included as an attachment.

Location

Overall Good:

Signs/Marker:

Type	OTHER				
Comment:	At well pad entrance. Photo 1.				
Corrective Action:					Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type					
Comment:	Note - Range cattle recently on site.				
Corrective Action:					Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type					
Comment:					
Corrective Action:					Date:

Equipment:

					corrective date
Type: Flow Line	# 1				
Comment:	insulated stainless.				
Corrective Action:					Date:
Type: Ancillary equipment	# 2				
Comment:	Cathodic protection and annular vent behind yellow vehicle barricade H-post.				
Corrective Action:					Date:
Type: Other	# 1				
Comment:	Wellhead.				
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	In well cellar. Accessible.				
Corrective Action:					Date:

Type: Ancillary equipment	# 1		
Comment:	telemetry		
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224508 Type: WELL API Number: 083-06573 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/14/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: In well cellar beneath grate.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100272	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488383