

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3223 Entrance to location



Photo # 3252 Battery sign is weathered & cracking/starting to become illegible

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3224 Location



Photo # 3232 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3249 Location



Photo # 3265 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3266 NE corner of location



Photo # 3267 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3268 SW corner of location



Photo # 3240 PRV vent line & Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3242 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3261 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #31-20-298 PAD

Location ID: 316473

Date: 03/17/2026



Photo # 3264 Tank battery fencing is in disrepair