

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON "B" #27X PAD

Location ID: 315966

Date: 03/16/2026



Photo # 3168 Entrance to location




Photo # 3170 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON "B" #27X PAD

Location ID: 315966

Date: 03/16/2026



Photo # 3171 Location



Photo # 3201 SW corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON "B" #27X PAD

Location ID: 315966

Date: 03/16/2026



Photo # 3202 NW corner of location



Photo # 3203 NE corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON "B" #27X PAD

Location ID: 315966

Date: 03/16/2026



Photo # 3204 SE corner of location



Photo # 3189 Failure to minimize erosion & transport of sediment on SW corner of location/berm needs maintenance

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON "B" #27X PAD

Location ID: 315966

Date: 03/16/2026



Photo # 3199 Failure to minimize erosion & transport of sediment on SW corner of location/berm needs maintenance




Photo # 3182 Debris

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC F V LARSON "B" #27X PAD

Location ID: 315966

Date: 03/16/2026



Photo # 3184 Debris