

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2026

Submitted Date:

03/16/2026

Document Number:

697012562

**FIELD INSPECTION FORM**

Loc ID 434314 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 25 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434312	WELL	PR	06/02/2015	OW	123-38088	Grant Hurt 1A-14H G268	PR
434313	WELL	PR	06/02/2015	OW	123-38089	Grant Hurt 1B-14H G268	PR
434315	WELL	PR	06/02/2015	OW	123-38090	Grant Hurt 1D-14H G268	PR
434316	WELL	PR	06/02/2015	OW	123-38091	Grant Hurt 1C-14H G268	PR
434317	WELL	PR	06/02/2015	OW	123-38092	Grant Hurt 1E-14H G268	PR
434318	WELL	PR	06/02/2015	OW	123-38093	Grant Hurt 1H-14H G268	PR
434319	WELL	PR	06/02/2015	OW	123-38094	Grant Hurt 1G-14H G268	PR
434380	WELL	PR	06/02/2015	OW	123-38131	Grant Hurt 1F-14H G268	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease road entrance sign is faded and illegible, see attached photo.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical systems require placards, see attached photos.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	06/19/2026
Type	BATTERY		
Comment:	Signs are faded and illegible, see attached photos.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	06/19/2026
Type	WELLHEAD		
Comment:	x 8. Signs are faded and illegible, see attached photos.		
Corrective Action:	Install signs to comply with Rule 605.	Date:	06/19/2026
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tanks require NFPA placards, see attached photos.		
Corrective Action:	Install signs to comply with Rule 605.	Date:	06/19/2026

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Tumble weeds around the location, see attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	06/19/2026

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chain link		
Corrective Action:		Date:	

Type	OTHER		
Comment:	Sound walls		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	Automation array, ECD scrubbers, chemical systems in secondary containment, supplied air system, electrical systems		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Western Midstream calibration card is current.		
Corrective Action:		Date:	
Type: Emission Control Device	# 6		
Comment:	Pilots are on		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	PBV FIBERGLASS		,
Comment:	250 bbls				
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	434312	Type:	WELL	API Number:	123-38088	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434313	Type:	WELL	API Number:	123-38089	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434315	Type:	WELL	API Number:	123-38090	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434316	Type:	WELL	API Number:	123-38091	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434317	Type:	WELL	API Number:	123-38092	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434318	Type:	WELL	API Number:	123-38093	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434319	Type:	WELL	API Number:	123-38094	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	434380	Type:	WELL	API Number:	123-38131	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Producing Well**

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	
		Tracking Pad	Pass			

Comment:

Corrective Action:

Date:

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Audit Report Summary</a>                      On Monday 3/16/2026 at approximately 10:55 hours I, Inspector Tom Peterson, conducted an on-site inspection at the Crestone Peak Grant Hurt 14H-G268 Pad in Weld County, Colorado.                      While there, I observed faded battery and wellhead signs, the produced water tanks required NFPA placards, the chemical systems required placards and debris on the location. During this inspection the following possible compliance issues were observed: Rule 605.with a corrective action date of 6/19/2026, Rule 606.with a corrective action date of 6/19/2026. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	petersont	03/16/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404582067	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7482021">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7482021</a>
697012563	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7482018">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7482018</a>