


QB ENERGY OPERATING LLC Federal 20-11 (PN20) Facility # 334682



**QB ENERGY OPERATING LLC
Federal 20-11 (PN20)
Facility # 334682**



Unused plug on top of tank.

**QB ENERGY OPERATING LLC
Federal 20-11 (PN20)
Facility # 334682**



Paint deterioration and areas of rust.




Rust on swedge and pipe fittings.

**QB ENERGY OPERATING LLC
Federal 20-11 (PN20)
Facility # 334682**



Paint deterioration and areas of rust.



Paint deterioration and areas of rust.

**QB ENERGY OPERATING LLC
Federal 20-11 (PN20)
Facility # 334682**



Dumpline excavated.

QB ENERGY OPERATING LLC Federal 20-11 (PN20) Facility # 334682



Dumpline excavated.

**QB ENERGY OPERATING LLC
Federal 20-11 (PN20)
Facility # 334682**



Dumpline excavated.




Dumpline excavated.

QB ENERGY OPERATING LLC Federal 20-11 (PN20) Facility # 334682





Separators shut in.

QB ENERGY OPERATING LLC Federal 20-11 (PN20) Facility # 334682



Stem broken off of valve.

**QB ENERGY OPERATING LLC
Federal 20-11 (PN20)
Facility # 334682**



Stem broken off of valve.