

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2026

Submitted Date:

03/18/2026

Document Number:

719500973

FIELD INSPECTION FORM

Loc ID 312511 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
9 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10770
 Name of Operator: VISION ENERGY LLC
 Address: P O BOX 370
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Vision		mollieo@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221818	WELL	TA	01/01/2021	GW	077-08420	FEDERAL 35-2	TA

General Comment:
 This is a field audit of the location, scout card, and related documents.
 On 3/16/2026 at approximately 15:15, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, FEDERAL-68S98W/35SENW at Location ID #312511 in Mesa County, Colorado.
 This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	No signs posted for location or any production equipment.		
Corrective Action:	Comply with CECMC Signs and Markers Rules.		Date: 03/25/2026
Emergency Contact Number:			
Comment:	911/(970)858-8550		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris present on location.		
Corrective Action:	Remove debris to comply with Rule 606.		Date: 07/12/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter on location.		
Corrective Action:	Remove unused equipment from location to comply with Rule 606.		Date: 08/08/2023
Type	WEEDS		
Comment:	Weeds are present across location.		
Corrective Action:	Remove weeds to comply with Rule 606.		Date: 07/12/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Livestock fencing		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 221818 Type: WELL API Number: 077-08420 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Ditches				
Compaction						
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Weeds are present across location 2) Debris on location 3) Unused equipment</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	03/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500974	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7489567