

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2026

Submitted Date:

03/17/2026

Document Number:

707801909

**FIELD INSPECTION FORM**

Loc ID: 324678      Inspector Name: Ramsey, Scott      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER      State: CO      Zip: 80203

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212402	WELL	PR	09/01/2021	OW	057-06295	MCCALLUM UNIT 111	PR

**General Comment:**

[ECMC Inspection Report Summary](#)

On Thursday 3/5/2026, I, Inspector Scott Ramsey, conducted a routine inspection/audit at KPK McCallum 111, at Location # 324678 in Jackson County Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Well signage lacks information.
2. Lacking belt guard

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment: 1. Well signage lacks information.

Corrective Action: a permanent sign will be conspicuously located at the wellhead and will identify:  
 A. The Well name;  
 B. The API number; and  
 C. Its legal location, including the quarter/quarter section.  
 When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign:  
 A. Name of the Operator;  
 B. Telephone number at which the Operator can be reached at all times;  
 C. Telephone number for local emergency services (911 where available); and  
 D. The public road used to access the Well.

Date: 04/17/2026

**Emergency Contact Number:**

Comment: 911/303-825-4822

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Lacking belt guard

Corrective Action: Eliminate possibility of wildlife or personnel from being harmed from equipment. Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.

Date: 04/17/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

Type: Bradenhead # 1 corrective date

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Type: Pump Jack # 1

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

Type \_\_\_\_\_

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 212402 Type: WELL API Number: 057-06295 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404583839	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483613">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483613</a>
707801915	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483607">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483607</a>