

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2026

Submitted Date:

03/17/2026

Document Number:

719500970

FIELD INSPECTION FORM

Loc ID 312470 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 10 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Vision		mollieo@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221711	WELL	PR	01/01/2016	GW	077-08313	FEDERAL 30-3	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 3/16/2026 at approximately 14:30, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, FEDERAL-68S97W/30SWSW at Location ID #312470 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Inaccurate Operator information on wellhead sign.		
Corrective Action:	Comply with CECMC Signs and Markers Rules.		Date: 04/18/2026
Emergency Contact Number:			
Comment:	911/(970)858-8550		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris present in multiple areas on location.		
Corrective Action:	Remove debris to comply with Rule 606.		Date: 07/12/2023
Type	WEEDS		
Comment:	Weeds are present across location.		
Corrective Action:	Remove weeds to comply with Rule 606.		Date: 07/12/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Livestock fencing		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas meter house is unsecured and poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 07/20/2023

Type: Horizontal Heated Separator	# 1		
Comment:	Wildlife entry into separator. A bird nest has been built in between separator wall and separation vessel.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 03/23/2026
Type: Horizontal Heated Separator	# 1		
Comment:	Gas leak on steel instrument tubing inside separator.		
Corrective Action:	Secure equipment to stop leak. 24 hour Corrective Action. Inspector notified Vision Energy office and field personnel.		Date: 03/18/2026

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 221711 Type: WELL API Number: 077-08313 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <ul style="list-style-type: none"> 1) Inaccurate Operator information on wellhead sign 2) Weeds present across location 3) Debris present on location 4) Gas leak on steel instrument tubing in separator 5) Wildlife entry into separator 6) Unsecured gas meter house <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	03/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404584064	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483745
719500971	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483742
719500972	Gas Leak in Separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483743