

Inspection Photos

Loc: 324901

Operator: RAMPIKE RESOURCES LTD

Inspection Date: 3/23/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the main road. The road is swaled and below the original grade of the terrain. There is concern for winter snow to blow onto the road impeding vehicle passage. This area of the road consists of sandy soil that needs to be stabilized with BMP's such as roadbase.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:324901 | Date: 3/23/2026

Inspection Photos



Photo 2. Facing east along the main access road. Red line is the approximate original grade and the shovel is 4.5 feet for scale. There is concern for winter snow to blow onto the road impeding vehicle passage.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:324901 | Date: 3/23/2026

Inspection Photos



Photo 3. The roadside has eroded and is not stabilized with vegetation. The sandy soils are susceptible to further erosion. This area needs to be repaired and stabilized.



Inspection Photos



Photo 4. Facing back to the west. At this point the road is compacted and stabilized.



Inspection Photos



Photo 5. Facing south along the access road.



Inspection Photos



Photo 6. Facing south toward the wellsite.



Inspection Photos



Photo 7. The operator sign has been updated.

