

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2026

Submitted Date:

03/24/2026

Document Number:

713602826

FIELD INSPECTION FORM

Loc ID 324800 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10777
Name of Operator: RAMPIKE RESOURCES LTD
Address: 730 17TH STREET SUITE 999
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
SHARP, NEIL		nsharp@rampikeresources.com	
		dnr_ecmc_complaints@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212683	WELL	PR	08/01/2024	OW	061-06043	DAWSON A 2	RI
324800	LOCATION	AC			-	DAWSON A-619S45W 9SWNW	RI

General Comment:

This is a reclamation inspection in regard to complaint #200452252 and #200452254.
The corrective action of the previous inspection has not been completed.
See attached photos and additional details within this report.

Location

Lease Road:

Type	Main		
comment:	This inspection was performed in response to complainants concern of conditions of the access roads. There are areas of the main road that are below the original topography grade. There are concerns with winter snow drifting onto the road impeding travel. Best Management Practices will need to be considered to maintain the road in a stable condition and to allow all weather access. BMP's may include: timely snow removal practices, snow fencing, regrading, ect. See Rules 603.I. and 1002.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	The well sign has been updated to reflect the current Operator.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 80%;" type="text"/>		
Corrective Action:	<input style="width: 80%;" type="text"/>	Date:	<input style="width: 50%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 212683 Type: WELL API Number: 061-06043 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324800 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Complaint

Comment: [Complaint ID: 200452252](#) Description: erosion of the road has made roads impassable after snow. cattle are forced to walk through or around the areas. Location Of Concern: lat 38.42431 long -102.470

[Complaint ID: 200452254](#) Description: erosion of the road has made roads impassable after snow storms which makes caring for cattle hard. cattle are forced to walk around or through dangerous spots. Location Of Concern: lat 38.41854, long -102.473

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the main roadside that has eroded and is not stabilized. There are sandy soils that are susceptible to further wind and stormwater erosion. The roadside will need to be repaired and stabilized. This area of the road consists of loose sandy soils and appropriate stabilization BMP's such as roadbase aggregate will be needed. See photos 3,4,7,8. Corrective action must be performed immediately.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Comply with Rule 1002.e.

Date: 02/20/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602827	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7491495