

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2026

Submitted Date:

03/24/2026

Document Number:

713602828

FIELD INSPECTION FORM

Loc ID 324901 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10777
Name of Operator: RAMPIKE RESOURCES LTD
Address: 730 17TH STREET SUITE 999
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
SHARP, NEIL		nsharp@rampikeresources.com	
		dnr_ecmc_complaints@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261344	WELL	PR	02/01/2024	OW	061-06784	HARRISON 7	RI
324901	LOCATION	AC			-	HARRISON-619S45W 9SENE	RI

General Comment:

This is a follow up inspection in regard to complaint #200452258 & #200452256.
The corrective action of the previous inspection has not been completed.
See attached photos and additional details within this report.

Location

Lease Road:

	Type Main		
comment:	This inspection was performed in response to complainants concern of conditions of the access roads. There are areas of the main road that are below the original topography grade. There are concerns with winter snow drifting onto the road impeding travel. Best Management Practices will need to be considered to maintain the road in a stable condition and to allow all weather access. BMP's may include: timely snow removal practices, snow fencing, regrading, ect. See Rules 603.I. and 1002.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

	Type		
Comment:	Well sign has been updated.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the main roadside that has eroded and is not stabilized. There are sandy soils that are susceptible to further wind and stormwater erosion. The roadside will need to be repaired and stabilized. This area of the road consists of loose sandy soils and appropriate stabilization BMP's such as roadbase aggregate will be needed. See photos 1,3. Corrective action must be performed immediately.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Comply with Rule 1002.e.

Date: 02/20/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602829	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7491496