

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2026

Submitted Date:

03/24/2026

Document Number:

717300847

FIELD INSPECTION FORM

Loc ID 321459 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| | | Inspections@civiresources.com | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|-------------------------|-------------|
| 272632 | WELL | SI | 11/01/2025 | GW | 013-06509 | VICKLUND G 32-2 | PA |
| 321459 | LOCATION | AC | | | - | VICKLUND G-61N69W 2SWNE | EG |

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photo uploaded

Inspected Facilities

Facility ID: 272632 Type: WELL API Number: 013-06509 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 321459 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Well is plugged and abandoned (Vicklund 32-2); ECMC form 42 notice of start of plugging operations doc #404509095 received on 01/16/2026. The facility/ tank battery is being decommissioned; tanks and equipment removed (contractors on site). No flowlines/ risers observed at PA well area. Remediation work is in progress. | maclarej | 03/24/2026 |
| As outlined on ECMC form 19 spill report Doc #404588595 received on 03/20/2026: During decommissioning historical impacts were discovered. | maclarej | 03/24/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 717300851 | Location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492270 |