

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2026

Submitted Date:

03/24/2026

Document Number:

721100278

## FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
306774 \_\_\_\_\_ Blair, Jamie \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: \_\_\_\_\_ 10749 \_\_\_\_\_  
Name of Operator: SIMCOE LLC \_\_\_\_\_  
Address: 1199 MAIN AVE SUITE 101 \_\_\_\_\_  
City: \_\_\_\_\_ DURANGO \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 81301 \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- \_\_\_\_ 20 \_\_\_\_\_ Number of Comments  
\_\_\_\_ 4 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Blair, Jamie		jamie.blair@state.co.us	
Natural, Mach		ehsinspections@machnr.com	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263958	WELL	PR	03/13/2018	CBM	067-08733	LARSEN 01-12 2	PR

**General Comment:**

On Tuesday March 24, 2026 at 15:30 hours, southwest compliance specialist Jamie Blair performed a producing well compliance inspection and audit. Corrective actions were identified. See attached photos.

<b>Location</b>			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location sign near gate. Photo 1.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Steel PBV Tank does not have volume label or hazcom placard. Content label is barely legible. Photo 12.		
Corrective Action:	Install signage to comply with Rule 605.h.		Date: 04/24/2026
Emergency Contact Number:			
Comment:	24 Hour - 970-247-6916. Emergency = 911.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	excessive dead vegetative debris in reclamation area and woody debris on pad. Photos 4, 17, 18.		
Corrective Action:	Comply with 606.		Date: 04/24/2026
Type	OTHER		
Comment:	Stained gravel beneath wellhead. Photo 6.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes to comply with 1002.f.		Date: 03/30/2026
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire and t post		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	cattle panel		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Cattle Panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date

Comment: <a href="#">Within 1 year = 7/10/25.</a>		Date:
Corrective Action:		Date:
Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment: <a href="#">on separator stack.</a>		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: <a href="#">Solar telemetry for pump jack and meter.</a>		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: <a href="#">accessible.</a>		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment: <a href="#">between tank, separator and meter.</a>		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: <a href="#">gas power.</a>		
Corrective Action:		Date:
Type: Other	# 1	
Comment: <a href="#">Wellhead. Stained soil beneath.</a>		
Corrective Action:		Date:
Type: Other	# 1	
Comment: <a href="#">Lube oil tank for prime mover has secondary containment tank with screen on top. Containment volume not adequate. Is nearly full, only 4 inches from top. Photo 8.</a>		
Corrective Action: <a href="#">Conduct maintenance on equipment, remove fluid from secondary containment and review self inspection processes to comply with 1002.f</a>		Date: <a href="#">03/30/2026</a>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.219572,-107.805139
Comment: <a href="#">Photo 12. Not labelled properly.</a>					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 263958 Type: WELL API Number: 067-08733 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Several Corrective Actions identified.</a> <a href="#">Includes Tank label, debris, stained soil, secondary containment on lube oil tank,</a> <a href="#">See attached photos</a> <a href="#">Any previous corrective actions may still apply.</a>	blairj1	03/24/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100279	Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492363">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492363</a>