

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2026

Submitted Date:

03/18/2026

Document Number:

716302052

**FIELD INSPECTION FORM**

Loc ID 307896 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**Findings:**

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
B ZECHES, GIENA		gzeches@ogrisop.com	<a href="#">All Inspections</a>
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259238	WELL	PR	09/04/2005	CBM	071-07211	HILL RANCH 22-12 V	PR
268803	PIT		07/25/2003		-	HILL RANCH 22-12V	

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 5 & 6: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE FROM LEAKING DRIVEHEAD.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 7: UNUSED EQUIPMENT (LARGE POLLY PIPE AND 2" POLLY PIPE AND EDGE OF PIT). PHOTO 8: UNUSED EQUIPMENT (PIPE ON EDGE OF PIT). PHOTO 9: UNUSED EQUIPMENT (HYDRALIC HOSE NEAR PRIME MOVER SOUND WALLS). PHOTO 10: UNUSED EQUIPMENT (2 PRIME MOVER HEADERS).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.		Date: 03/24/2026

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	30 BBL UNDER GROUND STEEL PRODUCED WATER TANK		
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	PHOTO 11: NO WILDLIFE PROTECTION INSTALLED ON 30 BBL INGROUND PRODUCED WATER TANK VENT.		
Corrective Action:	INSTALL BIRD PROTECTOR SCREEN OR OTHER DEVICE TO PROTECT WILDLIFE PER RULE 608b.(7).		Date: <u>03/24/2026</u>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 259238 Type: WELL API Number: 071-07211 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 268803 Type: PIT API Number: - Status: \_\_\_\_\_ Insp. Status: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:   
 Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 268803 Lat: 37.066690 Long: -104.880024  
 Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**  
 Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_  
 Comment:   
 Corrective Action  Date: \_\_\_\_\_

**Fencing:**  
 Fencing Type: None Fencing Condition: \_\_\_\_\_  
 Comment:   
 Corrective Action  Date: \_\_\_\_\_

**Netting:**  
 Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_  
 Comment:   
 Corrective Action  Date: \_\_\_\_\_  
 Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES  
 Comment:   
 Corrective Action  Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW-UP TO INSP.#698708255, ALL CA'S WHERE ADDRESSED WITH EXCEPTION OF LEAKING DRIVEHEAD, IMMEDIATE ACTION IS REQUIRED.                      ECMC Inspection Report Summary                      Date: 3/18/2026                      Time: 15:21                      Operator: Ogris Operating LLC.10758                      Location: HILL RANCH 22-12V                      API# 05-071-07211                      County: Las Animas County.                      While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: unused equipment, rule 606, 3/24/2026. mechanical condition of equipment, immediate action required. wildlife protection on vent, rule 608b.(7), 3/24/2026.follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	03/18/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404586299	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485820</a>
716302053	insp. photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485818">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485818</a>