

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2026

Submitted Date:

03/25/2026

Document Number:

718000075

FIELD INSPECTION FORM

Loc ID: 419648 Inspector Name: ALLISON, RICK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	All Inspection
Santistevan, Brittani		brittani.santistevan@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425995	TANK BATTERY	AC	10/04/2010		-	MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29	EI

General Comment:

ECMC Environmental Inspection of Tank Battery and Facility decommissioning. No equipment or signs remain on location. Site decommissioning activity resolves corrective actions from FIR 714202261.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Facility was decommissioned. No equipment remains except DCP riser and shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds appear resolved and site has been graded.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	An unknown stockpile of material is stored on the location. See attached photo. Operator to report disposition of this material on the required Supplemental Form 27.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 425995 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Operator has an approved site investigation and remediation workplan assigned Remediation Project 44481. Submit results of assessment no later than 6/25/2026 or report the discovery of a Release pursuant to Rule 912.b. and 913.f. if appropriate.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718000076	MoroFarmsTankBatteryPhotos3-25-2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493397