

# Inspection Photos

Facility: 478837

Operator: **KP Kauffman**

Inspection Date: 3/20/26 and 3/22/26

County: Weld



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Photo 1: Looking north (parallel to CR 19) at side slope towards Little Dry Creek. Corridor pictures locate flags for two KPK locates.**



**Photo 2: Looking south (parallel to CR 19) at valve cans depicting side slope towards Little Dry Creek. Corridor pictures locate flags for two KPK lines and DCP line from west to east.**

## Inspection Photos



Photo 3: Looking south - locate flags for only two lines south of valve cans.



Photo 4: Looking east at KPK, then DCP locate flags.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos



**Photo 5: Looking south at two smaller valve cans with third line entering corridor presumably from McCannon consolidation line across CR 19.**



**Photo 6: Unused pipe debris east of southern valve can.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources