

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2026

Submitted Date:

03/24/2026

Document Number:

715802108

**FIELD INSPECTION FORM**

Loc ID 318639 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241784	WELL	SI	08/01/2023	GW	123-09573	UPRR 43 PAN AM B 3	WK

**General Comment:**

This is a field audit of the scout card, related documents and the location.  
This Audit/Inspection is due to a form 42 MIRU doc # 404538410 & Fom 42 PA doc # 404538406.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	6' chainlink, well is in a fencing business.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241784 Type: WELL API Number: 123-09573 Status: SI Insp. Status: WK

**Cement**

Cement Contractor

Contractor Name: Brand-X Wireline Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 5,054, 4,610 Cement Volume (sx): 4

Good Return During Job: \_\_\_\_\_ Cement Type: G

Comment: Brand-X wireline is on location for P&A operations, currently prepping to set 2 CIBP. First CIBP set at 5,048' with 2 sxs cement on top perfs are at 5,104' the second CIBP set at 4,610' perfs are at 4,660' with 2 sxs cement on top.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

Comment: Piped to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: KP Kauffman WO rig on location for P&A operations, currently TOOHSB tubing in the derrick.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>This Audit/Inspection is due to a form 42 PA doc # 404538406.                      During this audit I witnessed KP Kauffman WO rig crew stand back 80 doubles in the derrick &amp; Brand-x set 2 CIBPs at 5,048' &amp; 4,610' setting 2 sxs cement on top of each..                      Weather: Partly cloudy/clear                      Temperature: 77*                      Location: Dry.</p>	revasr	03/24/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715802109	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493642">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493642</a>