

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2026

Submitted Date:

03/25/2026

Document Number:

719001707

**FIELD INSPECTION FORM**

Loc ID: 306780    Inspector Name: GARCIA, CHARLES    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON    State: TX    Zip: 77208

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264481	WELL	PR	01/20/2004	CBM	067-08747	THORNE 1-34-R	PR

**General Comment:**

Inspection Report Summary  
On 3/25/26 | Inspector Charles Garcia conducted an on-site inspection.  
Location: THORNE 1-34-R  
Operator:HILCORP ENERGY COMPANY  
API#: 067-08747  
County: LaPlata  
All prior CA's still stand

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	505-324-5170 911 EMERGENCY		Date:	
Corrective Action:				

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	SOUND WALLS		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SOUND WALLS		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 264481 Type: WELL API Number: 067-08747 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
NO ISSUES FOUND	garciacr1	03/25/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001708	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493795">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493795</a>