

Final Reclamation Inspection

March 17, 2026

Operator: KLABZUBA OIL & GAS INC - #10148

Location ID: 393816

Inspection Document #: 697506089

Morgan County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ADENA J SAND UNIT #W-54

Location ID: 393816



Photo 1. Photo taken from the well location, facing North. Photo illustrates an approximate 20' x 20' bare area; otherwise, vegetation meets Rule 1004 standards with the establishment of perennial, native grasses.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos

Location Name: ADENA J SAND UNIT #W-54

Location ID: 393816



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Red arrow points to used utility equipment- refer to Photos 5-6.



Inspection Photos

Location Name: ADENA J SAND UNIT #W-54

Location ID: 393816



Photo 5. Photo taken from the well location, illustrating unused utility equipment.



Photo 6. Photo taken from the well location. Photo illustrates the utility power has been disconnected and is no longer in use.



Inspection Photos

Location Name: ADENA J SAND UNIT #W-54

Location ID: 393816



Photo 7. Photo taken from the well location, facing North. Photo illustrates the access road vegetation meets Rule 1004 standards with the establishment of perennial, native grasses.



Inspection Photos

Location Name: ADENA J SAND UNIT #W-54

Location ID: 393816



Photo 8. Photo taken along another portion of the access road south of location, facing South. Photo illustrates the access road vegetation meets Rule 1004 standards with the establishment of perennial, native grasses.

