

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2026

Submitted Date:

03/20/2026

Document Number:

701104606

FIELD INSPECTION FORM

Loc ID 334766 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276618	WELL	PR	06/01/2022	GW	045-10495	GMR 9-14 (N9W)	EG
276619	WELL	PR	06/01/2022	GW	045-10496	HMU 9-13(N9W)	EG
412220	WELL	PR	06/01/2022	GW	045-18443	HMU 16-3A (N9W)	EG
412221	WELL	PR	06/01/2022	GW	045-18444	HMU 16-4(N9W)	EG
412222	WELL	PR	06/01/2022	GW	045-18445	ENCANA GMR 16-5 (N9W)	EG
412223	WELL	PR	06/01/2022	GW	045-18447	HMU 9-13B (N9W)	EG
412224	WELL	PR	06/01/2022	GW	045-18448	HMU 16-6A (N9W)	EG
412385	WELL	PR	06/01/2022	GW	045-18446	HMU 9-13C2 (N9W)	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
2 of 3 tanks have open outlets on top of them.
Comply with Rules 608.a.(10) Tank Venting Standards
CA Date 4/4/2026

Location

Lease Road:

Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLS	STEEL AST		,
Comment:	2 of 3 tanks have open outlets on top of them.				
Corrective Action:	Comply with Rules 608.a.(10) Tank Venting Standards			Date:	04/04/2026

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:				
Yes/No				
Comment:				
Corrective Action:			Date:	

Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities

Facility ID: 276618 Type: WELL API Number: 045-10495 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276619 Type: WELL API Number: 045-10496 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412220 Type: WELL API Number: 045-18443 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412221 Type: WELL API Number: 045-18444 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412222 Type: WELL API Number: 045-18445 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412223 Type: WELL API Number: 045-18447 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412224 Type: WELL API Number: 045-18448 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412385 Type: WELL API Number: 045-18446 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404588300	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487685
701104609	Flowline integrity inspection 701104606 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487681