

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2026

Submitted Date:

03/20/2026

Document Number:

710500755

FIELD INSPECTION FORM

Loc ID: 324809 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10777

Name of Operator: RAMPIKE RESOURCES LTD

Address: 730 17TH STREET SUITE 999

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Neal Sharp		nsharp@rampikeresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212814	WELL	PR	08/01/2022	OW	061-06174	BUTLER USA 1-X	EI
324809	LOCATION	AC			-	BUTLER USA-619S45W 10SWNE	EI

General Comment:

This is an Environmental Inspection for the Butler USA 1-X Well Location and Tank Battery located in Kiowa County, Colorado.

[Butler USA 1-X](#)
[Location ID: 324809](#)
[API 05-061-06174](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
Crude Oil	Separator			
<p>Comment: At the time of inspection, standing oil was observed within the secondary containment of the tank battery.</p> <p>In addition, oil mist was observed outside of the secondary containment along the southern edge of the location.</p> <p>ECMC reported the release of fluids to Rampike Lease Operator on 3/19/2026</p>				
Corrective Action: Isolate Immediately, 24-hours to remove free fluids. Control and contain spills/releases and clean up per Rule 912.a.			Date: <u>04/20/2026</u>	
Operator shall provide spill investigation details in a Field Inspection Report Resolution. (FIRR)				
Crude Oil	WELLHEAD			
<p>Comment: At the time of inspection, impacted soils were observed near the wellhead.</p>				
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.			Date: <u>04/20/2026</u>	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 212814 Type: WELL API Number: 061-06174 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324809 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404588796	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487999
710500756	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487995