

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2026

Submitted Date:

03/20/2026

Document Number:

715204170

FIELD INSPECTION FORM

Loc ID: 321748 Inspector Name: Welsh, Brian On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	EHS and Regulatory
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207906	WELL	TA	06/09/1997	OW	017-06841	FRONTERA UNIT 14-18 21	TA

General Comment:

SE Compliance Specialist Brian Welsh conducted a SI/TA status MIT
MIT FAILED. Contact ECMC Engineering for directives
Well is currently on the Operators internal P&A list. No Form 6 has been submitted at time of FAILED MIT

Location

Lease Road:

Type Access

comment: Trail through farm ground

Corrective ActionL

Date:

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: Lease sign by wellhead

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 207906 Type: WELL API Number: 017-06841 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: API# 05-017-06841
Extreme Heat pumped 70bbls water down the casing and well wouldn't load. Casing was on a vacuum when truck was unhooked. MIT FAILED

Corrective Action: Contact ECMC Engineering within 10 days for directives Date: 03/28/2026

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404589518	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488430
715204198	Form 21 MIT FAILED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488427