

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2026

Submitted Date:

03/20/2026

Document Number:

715204180

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 418350 _____ Welsh, Brian _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10267
 Name of Operator: VECTA OIL & GAS LTD
 Address: 575 UNION BLVD #208
 City: LAKEWOOD State: CO Zip: 80228

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Goolsby, Matt	303-618-7736	mdgoolsby@comcast.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418352	WELL	PR	04/01/2018	GW	017-07696	HURON 24-9	PR

General Comment:

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Labeling for tank is missing		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 04/19/2026
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds inside fence need to be maintained		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Hot wire fence around location		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Meter run on east side of tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Horizontal heated separator on north side of wellhead		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment at meter shed		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.839510,-102.677100

Comment: Water tank is on west side of meter shed

Corrective Action:	Date:
--------------------	-------

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Comment: Berms need repaired

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.	Date: 04/19/2026
--	--

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		
		Date:

Inspected Facilities

Facility ID: 418352 Type: WELL API Number: 017-07696 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Submit production reports for previous 6 months](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404589519	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488431
715204199	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488422
715204200	inadequate berms around tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488423
715204201	wellhead photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488424
715204202	wellhead is covered with weeds and grass	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488425