

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2026

Submitted Date:

03/24/2026

Document Number:

701104620

**FIELD INSPECTION FORM**

Loc ID: 335658      Inspector Name: LONGWORTH, MIKE      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER      State: CO      Zip: 80202

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283599	WELL	PR	08/01/2012	GW	045-11969	CHEVRON 36-1D	EG
283645	WELL	PR	01/01/2024	GW	045-11974	CHEVRON 36-2D	EG
283651	WELL	PR	08/01/2012	GW	045-11973	CHEVRON 36-3D	EG
284067	WELL	PR	09/10/2006	GW	045-12066	CHEVRON 36-4D	EG
284068	WELL	SI	02/01/2025	GW	045-12068	CHEVRON 36-6D	EG
284069	WELL	PR	07/06/2010	GW	045-12067	CHEVRON 36-5D	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Tanks paint has deterioration and areas of rust.  
Paint deterioration and rust where old label was on partially buried tank.  
One of the bolts is seeping from seal of man hatch.  
Inspect and repair man hatch seal on tank.  
CA Date 3/28/2026  
Buried tank is missing tank capacity.  
Install sign to comply with Rule 605.h.  
CA Date 4/25/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Buried tank is missing tank capacity.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/25/2026

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		,
Comment:	Paint deterioration and rust where old label was on partialy buried tank.				
Corrective Action:				Date:	

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,

Comment:	One of the bolts is seeping from seal of man hatch. Tanks paint has deterioration and areas of rust.	
Corrective Action:	Inspect and repair man hatch seal on tank.	Date: 03/28/2026

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 283599 Type: WELL API Number: 045-11969 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283645 Type: WELL API Number: 045-11974 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283651 Type: WELL API Number: 045-11973 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284067 Type: WELL API Number: 045-12066 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284068 Type: WELL API Number: 045-12068 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284069 Type: WELL API Number: 045-12067 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404593623	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7491711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7491711</a>
701104621	Flowline integrity inspection 701104620 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7491710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7491710</a>