

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2026

Submitted Date:

03/24/2026

Document Number:

721100278

FIELD INSPECTION FORM

Loc ID: 306774 Inspector Name: Blair, Jamie On-Site Inspection: 2A Doc Num: _____

Operator Information:
ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
20 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blair, Jamie		jamie.blair@state.co.us	
Natural, Mach		ehsinspections@machnr.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263958	WELL	PR	03/13/2018	CBM	067-08733	LARSEN 01-12 2	PR

General Comment:
On Tuesday March 24, 2026 at 15:30 hours, southwest compliance specialist Jamie Blair performed a producing well compliance inspection and audit. Corrective actions were identified. See attached photos.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Location sign near gate. Photo 1.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Steel PBV Tank does not have volume label or hazcom placard. Content label is barely legible. Photo 12.		
Corrective Action:	Install signage to comply with Rule 605.h.		Date: 04/24/2026
Emergency Contact Number:			
Comment:	24 Hour - 970-247-6916. Emergency = 911.		
Corrective Action:			Date:
Good Housekeeping:			
Type	DEBRIS		
Comment:	excessive dead vegetative debris in reclamation area and woody debris on pad. Photos 4, 17, 18.		
Corrective Action:	Comply with 606.		Date: 04/24/2026
Type	OTHER		
Comment:	Stained gravel beneath wellhead. Photo 6.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes to comply with 1002.f.		Date: 03/30/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire and t post		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	cattle panel		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Cattle Panel		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date

Comment: Within 1 year = 7/10/25.		Date:
Corrective Action:		Date:
Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment: on separator stack.		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: Solar telemetry for pump jack and meter.		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: accessible.		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment: between tank, separator and meter.		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: gas power.		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Wellhead. Stained soil beneath.		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Lube oil tank for prime mover has secondary containment tank with screen on top. Containment volume not adequate. Is nearly full, only 4 inches from top. Photo 8.		
Corrective Action: Conduct maintenance on equipment, remove fluid from secondary containment and review self inspection processes to comply with 1002.f		Date: 03/30/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.219572,-107.805139
Comment: Photo 12. Not labelled properly.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 263958 Type: WELL API Number: 067-08733 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Several Corrective Actions identified. Includes Tank label, debris, stained soil, secondary containment on lube oil tank, See attached photos Any previous corrective actions may still apply.	blairj1	03/24/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404594440	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492372
721100279	Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492363