

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: 03/31/2026 Submitted Date: 03/31/2026 Document Number: 719001722
FIELD INSPECTION FORM			

Loc ID 326636	Inspector Name: GARCIA, CHARLES	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10749 Name of Operator: SIMCOE LLC Address: 1199 MAIN AVE SUITE 101 City: DURANGO State: CO Zip: 81301				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260528	WELL	PR	06/29/2001	CBM	067-08500	TALIAFERRO TRUST A 2	PR

General Comment:

[Inspection Report Summary](#)
 On 3/31/26 | Inspector Charles Garcia conducted desk top follow up inspection.
 Location: TALIAFERRO TRUST A 2
 Operator: Simcoe LLC
 API#: 067-08500
 County: LaPlata
 All prior CA's still stand
 DOC#719001512
 FIR#404593030
 CAS RESOLVED

Inspected Facilities

Facility ID: 260528 Type: WELL API Number: 067-08500 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/13/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Meter calibration record not legible or conspicuously displayed at meter or meter not calibrated within the last 12 months Corrective Action: Display legible meter calibration record in conspicuous location to comply with rule CA RESOLVED SPILL PREVENTION FOR EXUAST FULL Corrective Action: Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used CA RESOLVED NO OTHER ISSUES FOUND</p>	garcia1	03/31/2026