

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2026

Submitted Date:

03/31/2026

Document Number:

719001723

FIELD INSPECTION FORM

Loc ID: 334007 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297885	WELL	PR	08/01/2024	CBM	067-09616	EE PRESTON 2	PR
297901	WELL	PR	08/01/2024	CBM	067-09618	EE PRESTON 4	PR

General Comment:

Inspection Report Summary
On 3/31/26 | Inspector Charles Garcia conducted an on-site inspection.
Location: EE PRESTON 4, EE PETERSON 2
Operator: Simcoe LLC
API#: 067-09616
API#: 067-09618
County: LaPlata
All prior CA's still stand
DOC#719001514
FIR#404593066
CA'S RESOLVED

Inspected Facilities

Facility ID: 297885 Type: WELL API Number: 067-09616 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/24/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 19 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297901 Type: WELL API Number: 067-09618 Status: PR Insp. Status: PR

Producing Well

Comment: _____
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/24/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
PRODUCED WATER TANK LABEL DAMAGED NOT LEGIBLE SEE LOCATION PICTURES Corrective Action: Replace/install labels/placards per Rule 605 CA RESOLVED	garciacr1	03/31/2026