

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>03/31/2026</u> Submitted Date: <u>03/31/2026</u> Document Number: <u>719001725</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID <u>320881</u> Inspector Name: <u>GARCIA, CHARLES</u> On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> ECMC Operator Number: <u>10749</u> Name of Operator: <u>SIMCOE LLC</u> Address: <u>1199 MAIN AVE SUITE 101</u> City: <u>DURANGO</u> State: <u>CO</u> Zip: <u>81301</u>		<b>Findings:</b> 3      Number of Comments 0      Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>		

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273594	WELL	PR	05/05/2015	CBM	007-06203	KERRIGAN 32-6-2 2	PR

**General Comment:**

[Inspection Report Summary](#)  
 On 3/31/26 | Inspector Charles Garcia conducted an desk top inspection.  
 Location: KERRIGAN 32-6-2 #2  
 Operator: Simcoe LLC  
 API#: 007-06203  
 County: ARCHULETA  
 DOC#719001230  
 FIR#404563720  
 CA'S RESOLVED

**Inspected Facilities**

Facility ID: 273594 Type: WELL API Number: 007-06203 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/16/2025 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CHEMICAL CONTAINER LABEL/PLACARD NOT LEGIBLE</b>                      Corrective Action: Install sign or correct sign per rule 605 CA RESOLVED  <b>DRY WEEDS INSIDE PRODUCED WATER TANK BERM AND BEHIND METER HOUSE AND SEPARATOR</b>                      Corrective Action: Keep areas around wellheads, tanks and separators clear of weeds (potentially combustible material) per Rule 610.k CA RESOLVED  <b>CHEMICAL INJECTION CONTAINER NO SPILL PREVENTION</b>                      Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.                      Comply with rule 1002.f CA RESOLVED</p>	garciacr1	03/31/2026