

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2026

Submitted Date:

03/25/2026

Document Number:

693809207

FIELD INSPECTION FORM

Loc ID: 316835 Inspector Name: BROWNING, CHUCK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM LLC
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harrison, Trish	970-759-9545	trish.harrison@coolskyenergy.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265250	WELL	TA	02/01/2025	GW	113-06115	ANDY'S MESA FEDERAL 30	TA

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On March 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Andy's Mesa Federal #30 well, API# 113-06115, Loc ID#3168835, in San Miguel County, Colorado.

The well was TA with flowline disconnected and blind flanged.

Form 42 - Start of Plugging Operations Doc#404467107 was received 12/10/2025. On 3/23/2026 No evidence of plugging operations were observed. Wellhead still intact in TA status. No corrective actions from previous inspection completed. See doc#693809100 submitted 12/20/2025.

During the inspection/audit, the following compliance issues were observed:

- 1) A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 per form 42 instructions. CA date 12/22/2025
- 2) Guy line anchors not marked - CA per Rule 1003.a, CA date 1/5/2026
- 3) Missing bird protectors on open ended flowline at tank battery - CA per Rule 608.b.(7), CA date 12/26/2025

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
Lease Road:			
Type	Access		
comment:	CR R25		
Corrective ActionL			Date:
Type	Main		
comment:	Hwy 141		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign on meter housing		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Dissconnected with bull plug		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Dissconnected with blind flange		
Corrective Action:			Date:

Type: Bird Protectors	# 1	
Comment:	Flowline inside tank berms open ended with no bird protection screen. CA from previous inspection not completed. CA date remains the same.	
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.	Date: 12/26/2025
Type: Deadman # & Marked	# 4	
Comment:	NW & SW guy line anchors not marked. CA from previous inspection not completed. CA date remains the same.	
Corrective Action:	Install proper guy line markers per Rule 1003.a. CA date 1/5/2026	Date: 01/05/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	Open Top		38.054988,-108.657149
Comment:	Screened open top blowdown tank inside metal berms.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 265250 Type: WELL API Number: 113-06115 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Form 42 - Start of Plugging Operations Doc#404467107 was recieved 12/10/2025.
No updated form on file. Well not plugged. CA date remains the same.

Corrective Action: A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 per Form 42 instructions. Date: 12/22/2025

BradenHead

Date of Last Brhd Test: 10/02/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>On March 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Andy's Mesa Federal #30 well, API# 113-06115, Loc ID#3168835, in San Miguel County, Colorado.</p> <p>The well was TA with flowline disconnected and blind flanged. Form 42 - Start of Plugging Operations Doc#404467107 was received 12/10/2025. On 3/23/2026 No evidence of plugging operations were observed. Wellhead still intact in TA status. No corrective actions from previous inspection completed. See doc #693809100 submitted 12/20/2025</p> <p>During the inspection/audit, the following compliance issues were observed: 1) A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 per form 42 instructions. CA date 12/22/2025 2) Guy line anchors not marked - CA per Rule 1003.a, CA date 1/5/2026 3) Missing bird protectors on open ended flowline at tank battery - CA per Rule 608.b.(7), CA date 12/26/2025</p>	browninc	03/25/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404595569	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493336
693809208	Inspection photos 3/23/2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493333