

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2026

Submitted Date:

03/25/2026

Document Number:

693809209

FIELD INSPECTION FORM

Loc ID: 316802 Inspector Name: BROWNING, CHUCK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM LLC
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Harrison, Trish	970-759-9545	trish.harrison@coolskyenergy.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232814	WELL	SI	05/01/2025	GW	113-06003	ANDY'S MESA-FEDERAL 4	SI

General Comment:

ECMC Inspection/Audit Report Summary

On March 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Andy's Mesa Federal #4 well, API# 113-06003, Loc ID#316802, in San Miguel County, Colorado.

The well was TA with flowline disconnected and blind flanged. Form 4 Doc#404540825 submitted 2/10/2026. Approved 2/11/2026 with completion deadline of 4/1/2026.

During the inspection/audit, the following compliance issues were observed:

- 1) Signs - CA from previous inspection completed. See inspection doc#693807705 submitted 8/30/2024
- 2) Guy line anchor on SW corner unmarked CA date 4/8/2026

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
Lease Road:			
Type	Access		
comment:	CR R25		
Corrective Action			Date:
Type	Main		
comment:	Hwy 141		
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	CA from previous inspection completed.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign on meter housing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Flowline disconnected and blind flanged		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Guy line anchor on SW corner unmarked		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 04/08/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		38.053869,-108.659410
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 232814 Type: WELL API Number: 113-06003 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well shut in 6/2024. Well TA with Flowline disconnected and blind flanged. Form 4 Doc#404540825 submitted 2/10/2026. Approved 2/11/2026 with completion deadline of 4/1/2026.

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 10/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 245 Fluid Type: NONE
End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>On March 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the Andy's Mesa Federal #4 well, API# 113-06003, Loc ID#316802, in San Miguel County, Colorado.</p> <p>The well was TA with flowline disconnected and blind flanged. Form 4 Doc#404540825 submitted 2/10/2026. Approved 2/11/2026 with completion deadline of 4/1/2026.</p> <p>During the inspection/audit, the following compliance issues were observed: 1) Signs - CA from previous inspection completed. See inspection doc#693807705 submitted 8/30/2024 2) Guy line anchor on SW corner unmarked CA date 4/8/2026</p> <p>Any corrective action(s) from previous inspection that have not been addressed are still applicable</p>	browninc	03/25/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404595572	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493337
693809210	Inspection photos 3/23/2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493334