

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2026

Submitted Date:

03/25/2026

Document Number:

701104624

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
334503 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|---------------------------------------|-----------------|
| COGCC, Laramie | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 278361 | WELL | PR | 01/25/2016 | GW | 077-08908 | MCDANIEL 2-6 | EG |
| 278362 | WELL | PR | 02/01/2015 | GW | 077-08909 | MCDANIEL 2-5 | EG |
| 278363 | WELL | PR | 12/02/2013 | GW | 077-08910 | MCDANIEL 2-4 | EG |
| 278364 | WELL | PR | 02/01/2015 | GW | 077-08911 | MCDANIEL 2-3 | EG |

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Paint on tanks are deteriorated with areas of rust corrosion.
Valve on separator for the 2-4 well is corroded in threads.
Inspect and repair or replace corroded valve.
Comply with Rule608.e.
CA Date 4/25/2026

Location

Lease Road:

| | | | |
|--------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|-------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | | | | |
|--------------------|---|-----|--|-------|-----------------|
| Type: | Horizontal Heated Separator | # 4 | | | corrective date |
| Comment: | Valve on separator for the 2-4 well is corroded in threads. | | | | |
| Corrective Action: | Inspect and repair or replace corroded valve. Comply with Rule608.e. | | | Date: | 04/25/2026 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 400 BBLs | STEEL AST | | , |
| Comment: | Paint on tanks are deteriorated with areas of rust corrosion. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|------------|--|
| Condition | Inadequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | | |
|--------------------|--|--|-------|--|
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Flaring:

| | | | | |
|--------------------|--|--|-------|--|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Inspected Facilities

Facility ID: 278361 Type: WELL API Number: 077-08908 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278362 Type: WELL API Number: 077-08909 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278363 Type: WELL API Number: 077-08910 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278364 Type: WELL API Number: 077-08911 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 404595653 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493406 |
| 701104625 | Flowline integrity inspection 701104624 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493396 |