

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2026

Submitted Date:

03/25/2026

Document Number:

701104628

FIELD INSPECTION FORM

Loc ID 334529 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278342	WELL	PR	08/01/2022	GW	077-08902	MCDANIEL 2-15	EG
278343	WELL	PR	01/01/2011	GW	077-08903	MCDANIEL 2-16	EG
278344	WELL	PR	08/01/2017	GW	077-08904	MCDANIEL 2-10	EG
278346	WELL	PR	09/21/2015	GW	077-08906	MCDANIEL 2-9	EG
292512	WELL	PR	07/01/2018	GW	077-09415	MCDANIEL 2-9A	EG
292513	WELL	PR	03/17/2009	GW	077-09414	MCDANIEL 2-10C	EG
292514	WELL	PR	08/01/2019	GW	077-09413	MCDANIEL 2-10B	EG
292515	WELL	PR	08/01/2025	GW	077-09412	MCDANIEL 2-10A	EG
292516	WELL	PR	09/10/2014	GW	077-09411	MCDANIEL 2-9C	EG
292517	WELL	PR	05/06/2014	GW	077-09410	MCDANIEL 2-9B	EG
292518	WELL	PR	03/17/2009	GW	077-09409	MCDANIEL 2-15C	EG
292519	WELL	PR	11/01/2025	GW	077-09408	MCDANIEL 2-15B	EG
292521	WELL	PR	07/16/2009	GW	077-09406	MCDANIEL 2-16C	EG
292522	WELL	PR	03/17/2009	GW	077-09405	MCDANIEL 2-16B	EG
292523	WELL	PR	01/25/2016	GW	077-09404	MCDANIEL 2-16A	EG

General Comment:

Fencing around plugged well excavation is sagging and inadequate.

Repair fence to protect wild life.

CA Date 3/28/2026

Storm water in plugged well excavation.

Remove storm water from excavation.

CA Date 3/28/2026

Corroded fittings and pipe sections on 6-2" risers running into the separator units.

2 - 2" well flowlines are corroded on McDaniel 2-10A and McDaniel 2-16 .

4 shut in risers and active dumpline risers at tank battery that have rust and corrosion.

Inspect corroded flowline. Repair or replace as necessary.

CA Date 04/25/2026

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Fencing around plugged well excavation is sagging and inadequate.		
Corrective Action:	Repair fence to protect wild life.		Date: 03/28/2026
Equipment:			
Type:	Flow Line	# 14	corrective date
Comment:	Corroded fittings and pipe sections on 6 risers running into the separator units. 2 - 2" well flowlines are corroded on McDaniel 2-10A and McDaniel 2-16 . 4 shut in risers and active dumpline risers at tank battery that have rust and corrosion.		
Corrective Action:	Inspect corroded flowline. Repair or replace as necessary.		Date: 04/25/2026
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 278342	Type: WELL	API Number: 077-08902	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 278343	Type: WELL	API Number: 077-08903	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 278344	Type: WELL	API Number: 077-08904	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 278346	Type: WELL	API Number: 077-08906	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292512	Type: WELL	API Number: 077-09415	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292513	Type: WELL	API Number: 077-09414	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292514	Type: WELL	API Number: 077-09413	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292515	Type: WELL	API Number: 077-09412	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292516	Type: WELL	API Number: 077-09411	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292517	Type: WELL	API Number: 077-09410	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292518	Type: WELL	API Number: 077-09409	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292519	Type: WELL	API Number: 077-09408	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292521	Type: WELL	API Number: 077-09406	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292522	Type: WELL	API Number: 077-09405	Status: PR	Insp. Status: EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 292523	Type: WELL	API Number: 077-09404	Status: PR	Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Storm water in plugged well excavation.](#)

Corrective Action: [Remove storm water from excavation.](#)

Date: 03/28/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404595656	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493407
701104629	Flowline integrity inspection 701104628 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493394