

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2026

Submitted Date:

03/25/2026

Document Number:

707801932

## FIELD INSPECTION FORM

Loc ID 335312	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 7 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: 10844 Name of Operator: QB ENERGY OPERATING LLC Address: 1001 17TH STREET SUITE 1600 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Cowden, Romana	720-951-5895	ecmc.inspections@qb-energy.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270263	WELL	PR	01/01/2020	GW	045-09502	LAZIER 26-2(H26NW)	PR
270271	WELL	SI	08/01/2022	GW	045-09514	BENZEL 26-7B (H26NW)	SI
270290	WELL	PR	02/01/2025	GW	045-09520	BENZEL 26-7B1 (H26NW)	PR
270292	WELL	PR	01/01/2020	GW	045-09521	BENZEL 26-7A (H26NW)	PR

**General Comment:**

ECMC Inspection Report Summary  
 On Monday 3/23/2026, I, Inspector Scott Ramsey, conducted a routine inspection/audit at QB H26NW, at Location # 335312 in Garfield County Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (QB) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:  
 1. Well signage lacks appropriate information.  
 Refer to photographs of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.  
 This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	1. Well signage lacks appropriate information.		
Corrective Action:	, A permanent sign will be conspicuously located at the wellhead and will identify: A. The Well name; B. The API number; and C. Its legal location, including the quarter/quarter section. When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: A. Name of the Operator; B. Telephone number at which the Operator can be reached at all times; C. Telephone number for local emergency services (911 where available); and D. The public road used to access the Well.		Date: 04/25/2026

<b>Emergency Contact Number:</b>	
Comment:	911/970-285-2615
Corrective Action:	
	Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:


Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:



**Inspected Facilities**

Facility ID: 270263 Type: WELL API Number: 045-09502 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270271 Type: WELL API Number: 045-09514 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270290 Type: WELL API Number: 045-09520 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270292 Type: WELL API Number: 045-09521 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No storm water BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404595658	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493409">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493409</a>
707801936	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7493399</a>