

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2026

Submitted Date:

04/02/2026

Document Number:

716302128

**FIELD INSPECTION FORM**

Loc ID 308301 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	<a href="#">Insp. w/ca's</a>
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265671	WELL	PR	03/28/2004	GW	071-07789	RAMPART 43-33	PR

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Progressive Cavity

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

# 4

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

Corrective Action:

Date:

Type: Compressor

# 1

Comment: PHOTO 4: TR WELLHEAD AND EQUIPMENT. Vacuum pump observed on well without ECMC approval.

Corrective Action: Provide ECMC with documentation showing approval of use of vacuum pump.

Date: 04/17/2026

**Venting:**

Yes/No NO

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 265671 Type: WELL API Number: 071-07789 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/09/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: FORM 4 BRHD SUNDRY IS ON FILE DOC #400678263.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 274265      Lat: 37.299940      Long: -104.779988

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	274265	1230362	
	274265	1230362	

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      Date: 4/2/2026                      Time: 13:40                      Operator: EVERGREEN NATURAL RESOURCES LLC 10705                      Location: RAMPART 43-33                      API# 05-071-07798                      County: Las Animas County.                      While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: VACUUM PUMP ON LOCATION WITHOUT ECMC APPROVAL, RULE 432, CA DATE 4/17/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	04/02/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302129	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503699">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7503699</a>