

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2026

Submitted Date:

04/02/2026

Document Number:

719700553

FIELD INSPECTION FORM

Loc ID 302512 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299103	WELL	TA	04/01/2020	OW	123-29257	BASHOR STATE AA 16-08	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
	Corrective Action:		Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Yellow LTSI tag posted. *Affix sign to well or fencing. *Refer to Emergency Contact Number section below.	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Emergency contact number with Company & Well Name NOT Legible. Refer to Rule 605.g for guidance.	
	Corrective Action:	*Post emergency contact number with Company & Well Name at wellsite. Comply with Rule 605.d. (30-days). 05/04/2026. See photo(s) #1.	Date: 05/04/2026

Overall Good:

Spills:			
	Type	Area	Volume
In Containment: No			
	Comment: <input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
	Type	WELLHEAD	
	Comment:	Iron panel.	
	Corrective Action:		Date:

Equipment:			
	Type: Plunger Lift	# 1	corrective date
	Comment:		
	Corrective Action:		Date:
	Type: Bradenhead	# 1	
	Comment:	Appears plumbed to surface.	
	Corrective Action:		Date:

Venting:			
	Yes/No	NO	
	Comment:		
	Corrective Action:		Date:

Flaring:			
	Type		

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 299103 Type: WELL API Number: 123-29257 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag posted at well.
ECMC records last prod: 08/2017.

Form 4 on file. TA date: 01/29/2019. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 01/01/2015.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 06/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On MON 03/30/2026 at approximately 15:02 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR STATE AA66N63W/16SENE Location ID: 302512 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>*CORRECTIVE ACTION ITEM(s): 1 1.) Refer to pg 2, "Signs/Marker" section of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	04/02/2026

<p>Comment 1: This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>Abandoned Centralized Battery formerly served 8 Location IDs (302510, 302509, 302511, 302512, 302513, 302517, 302521, 302540). (Well(s): 5: Temporarily Abandoned TA;3: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700553 and/or Location ID #302512 for TA Well(s) info. B.) Field Audit Report doc. #719700555 and/or Location ID #302509 for TA Well(s) info. C.) Field Audit Report doc. #719700557 and/or Location ID #302510 for TA Well(s) info. D.) Field Audit Report doc. #719700559 and/or Location ID #302511 for TA Well(s) info. E.) Field Audit Report doc. #719700561 and/or Location ID #302521 for TA Well(s) info. F.) Field Audit Report doc. #719700563 and/or Location ID #302517 for PA Well(s) info.</p>	<p>evinsb</p>	<p>04/02/2026</p>
---	---------------	-------------------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700554	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504064