

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2026

Submitted Date:

04/02/2026

Document Number:

719700563

FIELD INSPECTION FORM

Loc ID 302517 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299107	WELL	PA	04/04/2024	OW	123-29262	BASHOR STATE AA 16-17	PA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Plunger Lift	# 0			
Comment:	Plugged & Abandoned PA. Equipment removed.			
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: <input type="text"/>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 299107 Type: WELL API Number: 123-29262 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Comment 1: This is a PLUGGED & ABANDONED WELL audit. Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>Abandoned Centralized Battery formerly served 8 Location IDs (302510, 302509, 302511, 302512, 302513, 302517, 302521, 302540). (Well(s): 5: Temporarily Abandoned TA;3: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700553 and/or Location ID #302512 for TA Well(s) info. B.) Field Audit Report doc. #719700555 and/or Location ID #302509 for TA Well(s) info. C.) Field Audit Report doc. #719700557 and/or Location ID #302510 for TA Well(s) info. D.) Field Audit Report doc. #719700559 and/or Location ID #302511 for TA Well(s) info. E.) Field Audit Report doc. #719700561 and/or Location ID #302521 for TA Well(s) info. F.) Field Audit Report doc. #719700563 and/or Location ID #302517 for PA Well(s) info.</p>	evinsb	04/02/2026
<p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On MON 03/30/2026 at approximately 15:30 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR STATE AA-66N63W/16SENE Location ID: 302517 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.486284 / -104.432985</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 04/04/2024. Approved. Plugged & Abandoned PA well GPS coordinates: 40.490237 / -104.437237 Form 27 on file. Date: 11/18/2025. Approved.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	04/02/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700564	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504069