

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2026

Submitted Date:

03/27/2026

Document Number:

701104633

FIELD INSPECTION FORM

Loc ID: 312652 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222087	WELL	PR	04/01/2025	GW	077-08689	CASTLE ROCK 18-4	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Gas leak from hammer union seal around tubing/production annulus. Tubing has a tag with no visible info.
Contacted Matt Kastan with Laramie by email.
Laramie discovered leak 8/6/2026 and repaired 8/8/2026. Matt has notified FLIR camera team to respond and repair leak.
Repair leak. Comply wit Rule 608.e..
CA Date 4/30/2026

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:					
Corrective Action:				Date:	

Paint

Condition

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 222087 Type: WELL API Number: 077-08689 Status: PR Insp. Status: EG

Producing Well

Comment: [Gas leak from hammer union seal around tubing/production annulus. Tubing has a tag with no visible info. Contacted Matt Kastan with Laramie by email. Laramie discovered leak 8/6/2026 and repaired 8/8/2026. Matt has notified FLIR camera team to respond and repair leak.](#)

Corrective Action: [Repair leak. Comply wit Rule 608.e..](#)

Date: 04/30/2026

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404597782	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7495286
701104634	Audio and video of tubing seal leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7495275
701104635	Flowline integrity inspection 701104633 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7495276