

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2026

Submitted Date:

03/27/2026

Document Number:

716302092

FIELD INSPECTION FORM

Loc ID 333937 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
B ZECHES, GIENA		gzeches@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259038	WELL	PR	11/01/2022	CBM	071-07182	HILL RANCH 27-12 V	PR
259039	WELL	PR	05/30/2003	CBM	071-07183	HILL RANCH 27-12 R	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 7: ALLTHOUGH IT APPEARS THAT THE CA FROM PREVIOUS INSPECTION WAS ADDRESSED THE CONDITIONS THAT CREATED THE CA STILL EXISTS ON V WELL.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer's recommended specifications per Rule 608.e.	Date:	04/02/2026
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 6: UNUSED EQUIPMENT (PRIME MOVER ENGINE SKIT IS NOT USABLE ON R WELL).		
Corrective Action:	THIS TYPE OF WORK CANNOT BE PERFORMED ON LOCATION. REMOVE UNUSED EQUIPMENT PER RULE 606.	Date:	04/02/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Count	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 8				
Comment:					
Corrective Action:					
Type: Prime Mover	# 3				
Comment:		SEE HOUSE KEEPING FOR DETAILS ON CORRECTIVE ACTIONS.			
Corrective Action:					
Type: Gas Meter Run	# 2				
Comment:		BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:					
Type: Bradenhead	# 2				
Comment:		BOTH ARE ACCESSABLE			
Corrective Action:					
Type: Ancillary equipment	# 2				
Comment:					
Corrective Action:					

Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 259038 Type: WELL API Number: 071-07182 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259039 Type: WELL API Number: 071-07183 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [PHOTO 8: OILY WASTE IN PRIME MOVER ENGINE SKIDWITHOUT WILDLIFE PROTECTIONS ON R WELL.](#)

Corrective Action: [DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..\(2\).D & 1002.f.\(2\)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.](#)

Date: 03/28/2026

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 268821 Lat: 37.053150 Long: -104.880201

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____
 Corrective _____

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____
 Corrective _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____
 Corrective _____

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____
 Corrective _____

Date: _____

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary Date:3/27/2026 Time: 12:33 Operator: Ogris Operating LLC.10758 Location: HILL RANCH 27-12 TR & V API# 05-071-07183 & 7182 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: UNUSED EQUIPMENT, RULE 606, CA DATE 4/2/2026. MECHANICAL EQUIPMENT LEAK, Rule 608.e. CA DATE 4/2/2026. OILY WASTE IN SKID, RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 3/28/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.	beardslt	03/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404598381	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7495871
716302093	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7495870