

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2026

Submitted Date:

04/03/2026

Document Number:

719700565

**FIELD INSPECTION FORM**

Loc ID 310240 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291667	WELL	TA	04/10/2020	OW	123-26118	BASHOR STATE AA 16-6	TA

**General Comment:**

*\*This is an audit of the scout card and related documents followed by a field audit.*

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Post TA tag at well.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted. Emergency number peeling. Consider replacing.		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 291667 Type: WELL API Number: 123-26118 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Battery Abandoned.  
Locked-Out, Tagged-Out | LOTO.  
ECMC records last prod: 07/2016.  
  
Form 4 on file. TA date: 03/20/2018. Approved.  
Form 6A on file. Out-of-Svc Designation. Approved.  
Date ceased prod: 08/01/2015.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/05/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>Comment 1:</b>                      This is a WELL audit.                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Abandoned. ALL equipment has been removed.                      Abandoned Battery SE corner GPS coordinates: 40.487151 / -104.449574</p> <p>Abandoned Centralized Battery formerly served 7 Location IDs (310240, 302508, 302516, 302522, 310238, 310241, 310243).                      (Well(s): 1: Temporarily Abandoned   TA;6: Plugged &amp; Abandoned   PA).</p> <p>Reference (Associated Well(s), Battery / Facility Audits):                      A.) Field Audit Report doc. #719700565 and/or Location ID #310240 for TA Well(s) info.                      B.) Field Audit Report doc. #719700567 and/or Location ID #302508 for PA Well(s) info.                      C.) Field Audit Report doc. #719700569 and/or Location ID #302516 for PA Well(s) info.                      D.) Field Audit Report doc. #719700571 and/or Location ID #310238 for PA Well(s) info.                      E.) Field Audit Report doc. #719700573 and/or Location ID #310241 for PA Well(s) info.                      F.) Field Audit Report doc. #719700575 and/or Location ID #310243 for PA Well(s) info.                      G.) Field Audit Report doc. #719700577 and/or Location ID #302522 for PA Well(s) info.</p>	evinsb	04/03/2026

<p><b>Comment 2:</b>  <b>CECMC Audit Report Synopsis:</b></p> <p>On MON 03/30/2026 at approximately 16:14 hrs. I, Bret Evins, conducted an onsite audit at:  <b>Operator Name:</b> NOBLE ENERGY INC  <b>Location Name:</b> BASHOR STATE AA-66N63W/16SENW  <b>Location ID:</b> 310240  <b>Well Name(s) &amp; API:</b>  <b>Reference:</b>                  See "Inspected Facilities" section on page 1 of this report.  <b>Location County:</b> Weld County, Colorado  <b>Weather:</b> Partly Sunny, dry.</p> <p>While there, I observed:  <b>Well(s):</b> 1: Temporarily Abandoned   TA.  <b>Battery:</b> Abandoned. ALL equipment has been removed.                  Abandoned Battery SE corner GPS coordinates: 40.487151 / -104.449574</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	04/03/2026
---	--------	------------

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700566	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504564</a>