

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2026

Submitted Date:

04/03/2026

Document Number:

719700579

FIELD INSPECTION FORM

Loc ID 306256 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 287392 | WELL | TA | 01/01/2019 | OW | 123-24307 | PEPLER 17-34 | TA |

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:

| | | | | | |
|--------------------|----------|--|--|-------|--|
| Type | Access | | | | |
| comment: | Adequate | | | | |
| Corrective Action: | | | | Date: | |

Overall Good:

Signs/Marker:

| | | | | | |
|--------------------|----------------------|--|--|-------|--|
| Type | WELLHEAD | | | | |
| Comment: | Post TA tag at well. | | | | |
| Corrective Action: | | | | Date: | |

Emergency Contact Number:

| | | | | | |
|--------------------|---|--|--|-------|--|
| Comment: | Posted. Emergency number peeling. Consider replacing. | | | | |
| Corrective Action: | | | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | | | |
|--------------------|-------------|--|--|-------|--|
| Type | WELLHEAD | | | | |
| Comment: | Iron panel. | | | | |
| Corrective Action: | | | | Date: | |

Equipment:

| | | | | corrective date |
|--------------------|-----------------------------|--|--|-----------------|
| Type: Bradenhead | # 1 | | | |
| Comment: | Appears plumbed to surface. | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | | | |
|--------------------|----|--|--|-------|--|
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Flaring:

| | | | | | |
|--------------------|--|--|--|-------|--|
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Inspected Facilities

Facility ID: 287392 Type: WELL API Number: 123-24307 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
ECMC records last prod: 05/2016.

Form 4 on file. TA date: 12/10/2018. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 01/01/2015.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 03/18/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| Reclamation - Storm Water - Pit | | | | | | |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------|
| Storm Water: | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | | | | | |
| Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> | | | | | | Date: _____ |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

| ECMC Comments | | |
|--|--------|------------|
| Comment | User | Date |
| <p>Comment 1: This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.479495 / -104.461296</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (306256, 306258, 306259, 419032). (Well(s): 1: Temporarily Abandoned TA;3: Plugged & Abandoned PA).</p> | evinsb | 04/03/2026 |
| <p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On MON 03/30/2026 at approximately 17:21 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: PEPPLER-66N63W /17SESW Location ID: 306256 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.479495 / -104.461296</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p> | evinsb | 04/03/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 719700580 | Audit photo(s) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504571 |