

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2026

Submitted Date:

04/03/2026

Document Number:

713302575

FIELD INSPECTION FORM

Loc ID 336651 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------|---------------------------------|
| , KPK | 303-825-4822 | cogcc@kpk.com | all inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 250003 | WELL | PR | 03/01/2019 | GW | 123-17806 | OCOMA 31-27 | PR |

General Comment:

[follow up inspection](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | good | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | metal panels | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | | |
|---------------------------|--|-------|--|--|-----------------|
| | | | | | corrective date |
| Type: Plunger Lift | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | piped to surface | | | | |
| Corrective Action: | | Date: | | | |
| Type: Ancillary equipment | # 3 | | | | |
| Comment: | automation panels, wind whip to peices | | | | |
| Corrective Action: | | Date: | | | |
| Type: Deadman # & Marked | # 3 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|----------|--|--|--|
| Type | | | |
| Comment: | | | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 250003 Type: WELL API Number: 123-17806 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 08/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|--|---------|------------|
| <u>Audit of scout card and related documents</u> | kesterm | 04/03/2026 |
| <u>Follow up inspection as per Doc # 717701669, corrective actions appeared to have been addressed</u> | | |
| <u>This inspection does not nullify any orders or NOAV from the ECMC</u> | | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713302576 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505132 |