


**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**1. Well location sign.**

**2. Well location entrance. Large puddle inside gate. Gate was open at time of inspection.**

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**3. Pile of vegetative debris in NE corner of well pad piled against corner of fence.**



**4. Pump jack, wellhead, chemical treatment tanks over secondary containment.**

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**5. Wellhead.**

**6. Chemical treatment container.**

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**7. Chemical treatment container. Lacks labels indicating contents and volume. Has an MSDS-like label that is peeling and difficult to read with some indication of flammability but no NFPA Diamond.**

**8. Generator power for electric prime mover inside sound barrier structure. Was operating at time of inspection.**


Inspection Photos  
Location Name: Enduring Resources  
Location ID: Koshak # B-4A. API 05-067-08763



9. Pumpjack and electric prime mover.

10. Open-topped 95 BBL steel produced water tank inside berm. Berm is adequate. Tank has necessary labels.

Inspection Photos  
Location Name: Enduring Resources  
Location ID: Koshak # B-4A. API 05-067-08763



11. Additional tank labels and NFPA diamond.

12. Flow lines with valves. Pin flags should be removed when no longer needed.

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**13. Meter calibration card dated 1/15/2026.**

**14. Well location overview looking SE.**

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**15. Chain link fence on west edge of pad. Unused fence gate segment.**

**16. Flow lines, meter run, and telemetry. Note pin flags.**

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**17. Location perimeter berm.**

**18. Location Perimeter berm.**

**Inspection Photos**  
**Location Name: Enduring Resources**  
**Location ID: Koshak # B-4A. API 05-067-08763**



**19. Location perimeter berm.**

**20. Overview looking northwest from perimeter berm in southwest corner.**