

Final Reclamation Inspection

March 20, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336577

Inspection Document #: 718801509

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: BOHLENDER JACOB T. UNIT

A-63N66W/14SWSE

Location ID: 336577



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed at the location.



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: BOHLENDER JACOB T. UNIT

A-63N66W/14SWSE

Location ID: 336577



Photo 3. Photo taken of the multi-well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west. See comments under Photo 1.



Inspection Photos

Location Name: BOHLENDER JACOB T. UNIT

A-63N66W/14SWSE

Location ID: 336577



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



Photo 6. Photo taken of the multi-well location, facing southeast. See comments under Photo 1.



Inspection Photos

Location Name: BOHLENDER JACOB T. UNIT

A-63N66W/14SWSE

Location ID: 336577



Photo 7. Photo taken of the access road to the location, facing northeast. Photo illustrates that reclamation activities appear to have taken place along the road, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed.



Photo 8. Photo taken of the reference area to the location, south of the location, facing southeast. Photo illustrates perennial grass and weedy annual vegetation.

