

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2026

Submitted Date:

04/06/2026

Document Number:

719700589

FIELD INSPECTION FORM

Loc ID 419444 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419452	WELL	TA	04/01/2020	OW	123-32256	BASHOR PC AA17-24	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:	Yellow LTSI tag posted.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted. *Emergency number peeling. Consider replacing.		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 419452 Type: WELL API Number: 123-32256 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag posted at well.
ECMC records last prod: 08/2016.

Form 4 on file. TA date: 12/05/2018. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 05/15/2015.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 04/25/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>Comment 1: This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.484920 / -104.460460</p> <p>Abandoned Centralized Battery formerly served 10 Location IDs (419444, 305753, 305758, 306260, 306263, 306264, 419449, 419494, 419566, 444901). (Well(s): 5: Temporarily Abandoned TA;5: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700589 and/or Location ID #419444 for TA Well(s) info. B.) Field Audit Report doc. #719700591 and/or Location ID #306263 for TA Well(s) info. C.) Field Audit Report doc. #719700593 and/or Location ID #444901 for TA Well(s) info. D.) Field Audit Report doc. #719700595 and/or Location ID #306260 for TA Well(s) info. E.) Field Audit Report doc. #719700597 and/or Location ID #306264 for TA Well(s) info. F.) Field Audit Report doc. #719700599 and/or Location ID #419566 for PA Well(s) info. G.) Field Audit Report doc. #719700601 and/or Location ID #419494 for PA Well(s) info. H.) Field Audit Report doc. #719700603 and/or Location ID #305758 for PA Well(s) info. I.) Field Audit Report doc. #719700605 and/or Location ID #419449 for PA Well(s) info.</p>	evinsb	04/06/2026

<p>Comment 2: CECMC Audit Report Synopsis:</p> <p>On WED 04/01/2026 at approximately 11:38 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR PC /AA17-24 Location ID: 419444 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.484920 / -104.460460</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	<p>evinsb</p>	<p>04/06/2026</p>
--	---------------	-------------------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700590	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7506209