

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2026

Submitted Date:

04/07/2026

Document Number:

717300894

FIELD INSPECTION FORM

Loc ID 327350 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246750	WELL	PA	11/25/2025	OW	123-14547	THOMSEN-USX X 7-4	PA
289813	WELL	PA		GW	123-24924	THOMSEN-USX X 7-6	PA
464010	TANK BATTERY	AC	04/18/2019		-	Thomsen USX 7-3, -4, -6 & 12 battery	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 246750 Type: WELL API Number: 123-14547 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289813 Type: WELL API Number: 123-24924 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 464010 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Wells are PA (Thomsen 7-4, 7-6); ECMC form 42 notice of start of plugging operations doc #404341080 received 09/04/2025. Wellhead OLF's have been removed; bellhole excavations observed at flowline pipe removal pull points between WH & battery (backfilled). Facility decommissioning work is completed; flowline removal work (on location/ facility) is completed. ECMC form 42 notice of flowline abandonment completed doc #404454116 received on 12/01/2025. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work (at facility) is in progress.	maclarej	04/07/2026
As outlined on ECMC form 19 spill report Doc #404601374 received on 04/02/2026: While conducting wellhead plugging and abandonment and flowline removal activities at the Thomsen-USX X 7-6 wellhead, historically impacted soil was discovered at the flowline sample FL02. The volume of the release is unknown. The flowline will be permanently removed.	maclarej	04/07/2026
As outlined on ECMC form 19 spill report Doc #404601370 received on 04/02/2026: While conducting wellhead plugging and abandonment and flowline removal activities at the Thomsen-USX X 7-6 wellhead, historically impacted soil was discovered at the flowline sample FL03. The volume of the release is unknown. The flowline will be permanently removed.	maclarej	04/07/2026
As outlined on ECMC form 19 spill report Doc #404601366 received on 04/02/2026: While conducting wellhead plugging and abandonment and flowline removal activities at the Thomsen-USX X 7-6 wellhead, historically impacted soil was discovered at the flowline sample FL04. The volume of the release is unknown. The flowline will be permanently removed.	maclarej	04/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300900	Excavation and signage at facility/ battery; No FL's	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7506880
717300901	Excavation/ remediation; OLF removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7506881